

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2024

Submitted Date:

12/23/2024

Document Number:

699805777

FIELD INSPECTION FORM

Loc ID 312710 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10310

Name of Operator: FRAM OPERATING LLC

Address: 5525 N UNION BLVD #200

City: COLORADO State: CO Zip: 80918

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277504	WELL	SI	04/24/2009	GW	077-08872	DOTY 1-1 (OWP)	PA

General Comment:

ECMC Inspection Report Summary

On 7/12/2024 I, West OWP Supervisor Corey DePaolo,

Witnessed the plugging and abandonment of the FRAM OPERATING LLC DOTY 1-1 (OWP)

Location #312710 in Mesa County Colorado.

-OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/12/2024.

This is a summary of the inspection report

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	All signs removed from location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other	#			corrective date
Comment:	All equipment has been removed from location.			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	277504	Type:	WELL	API Number:	077-08872	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Delsco Northwest				Contractor Phone:					
Surface Casing									
Cement Volume (sx):				Circulate to Surface:					
Cement Fall Back:				Top Job, 1" Volume:					
Intermediate Casing									
Cement Volume (sxs):				Good Return During Job:					
Production Casing									
Cement Volume (sx):				Good Return During Job:					
Plugging Operations									
Depth Plugs(feet range): 1887' to 0'				Cement Volume (sx): 57					
Good Return During Job: YES				Cement Type: G					
Comment:				OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one CICR and surface. The well was cut and capped on 7/12/2024.					
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Refer to Related Facility for comments,	depaoloc	12/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805777	INSPECTION APPROVED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839919
699805778	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839907