

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2024

Submitted Date:

12/23/2024

Document Number:

699805781

FIELD INSPECTION FORM

Loc ID 334484 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:

Operator Information:

ECMC Operator Number: 10310

Name of Operator: FRAM OPERATING LLC

Address: 5525 N UNION BLVD #200

City: COLORADO State: CO Zip: 80918

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291118	WELL	TA	12/01/2018	GW	077-09314	Eberly (OWP) 23-4-M	PA

General Comment:

ECMC Inspection Report Summary

On 6/07/2024 I, West OWP Supervisor Corey DePaolo,
Witnessed the plugging and abandonment of the FRAM OPERATING LLC EBERLY #23-4-M (OWP)
Location #334484 in Mesa County Colorado.

-OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one balance and surface. The well was cut and capped on 6/07/2024.

This is a summary of the inspection report

Location					
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	OTHER				
Comment:	All signs have been removed				
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>			Date:	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:	<input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Other	#			corrective date	
Comment:	All equipment has been removed from location				
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	291118	Type:	WELL	API Number:	077-09314	Status:	TA	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Delsco Northwest					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 1705' to 0'					Cement Volume (sx): 59				
Good Return During Job: YES					Cement Type: G				
Comment: OWP Plugging operations consisted of setting 3 plugs over 2 days. One CIBP, one balance and surface. The well was cut and capped on 6/07/2024.									
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Refer to related facility for comments.	depaoloc	12/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805781	INSPECTION APPROVED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839921
699805782	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839909