

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2024

Submitted Date:

12/23/2024

Document Number:

699805783

FIELD INSPECTION FORMLoc ID 322011 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10310

Name of Operator: FRAM OPERATING LLC

Address: 5525 N UNION BLVD #200

City: COLORADO State: CO Zip: 80918

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaulo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286534	WELL	SI	10/31/2006	GW	029-06101	HAMILTON 32-4 (OWP)	PA

General Comment:

ECMC Inspection Report Summary

On 8/16/2024 I, West OWP Supervisor Corey DePaolo,

Witnessed the plugging and abandonment of the FRAM OPERATING LLC HAMILTON#32-4 (OWP)

Location #322011 in Delta County Colorado.

-OWP Plugging operations consisted of setting 3 plugs over 2 days. Two CIBP and surface. The well was cut and capped on 8/16/2024.

This is a summary of the inspection report

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type		OTHER		
Comment:		All sign have been removed from location		
Corrective Action:		Date:		
Emergency Contact Number:				
Comment:				
Corrective Action:		Date: _____		
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other		#		corrective date
Comment:		All equipment has been removed from location		
Corrective Action:		Date:		
Venting:				
Yes/No				
Comment:				
Corrective Action:		Date:		
Flaring:				
Type				
Comment:				
Corrective Action:		Date:		

Inspected Facilities									
Facility ID:	286534	Type:	WELL	API Number:	029-06101	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Delsco Northwest					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 2957' to 0'					Cement Volume (sx): 143				
Good Return During Job:					Cement Type: G				
Comment: OWP Plugging operations consisted of setting 3 plugs over 2 days. Two CIBP and surface. The well was cut and capped on 8/16/2024.									
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Refer to related facility for comments	depaoloc	12/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805783	INSPECTION APPROVED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839922
699805784	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839910