

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2024

Submitted Date:

12/23/2024

Document Number:

717300156**FIELD INSPECTION FORM**Loc ID 321404 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206769	WELL	TA		GW	014-06264	MAPZ MD 13-1J	PA
206873	WELL	SI	12/01/2020	OW	013-06368	MAPZ MD 13-2	PA
460818	Location	AC			-	Mapz MD 13-1J, 2	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 206769 Type: WELL API Number: 014-06264 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 206873 Type: WELL API Number: 013-06368 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 460818 Type: Location API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
(2) Wells are plugged and abandoned (Mapz MD 13-2, 13-IJ); ECMC form 42 notice of start of plugging operations (13-2) doc #403954732 recieved 10/11/2024. No flowlines and/ or flowline risers observed at PA well or facility/ battery areas. Bellhole excavations observed at flowline removal points between the 13-2 PA well and facility (OLF/ backfilled). The facility/ tank battery has been decommissioned/ equipment removed; on location dump and process flowlines at facility/ battery are removed. Note: (2) steel AST production tanks on location at time of inspection (disconnected/ to be removed). Remediation work is in progress.	maclarej	12/19/2024
As outlined on ECMC form 19 spill report Doc #404032017 received on 12/17/2024: While conducting facility decommissioning activities at Extraction's Mapz MD 13-1J, 2 tank battery, historical impacts were discovered at the former produced water vault. The impacted soil will be removed and hauled for disposal. Lease operators are coached to conduct routine AVO inspections at all oil and gas locations.	maclarej	12/19/2024
As outlined on ECMC form 19 spill report Doc #404031987 received on 12/17/2024: While conducting facility decommissioning activities at Extraction's Mapz MD 13-2 wellhead, historical impacts were discovered. The impacted soil will be removed and hauled for disposal.	maclarej	12/19/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300156	INSPECTION APPROVED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839811
717300158	PA well (13-2); view SE (OLF BH backfilled)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839808
717300159	View of location; production tanks to be removed	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6839809