

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 5649 From entrance to location




Photo # 5650 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 5651 Location



Photo # 5652 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 5653 Location



Photo # 5654 Open ended piping/wildlife hazard/available for entry by wildlife

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9377 From inspection 708903976 conducted on 06/05/2024 Open ended load line



Photo # 5655 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



**Photo # 5656 Open ended piping & netting also needs maintenance/available for entry by wildlife/wildlife hazards**



**Photo # 5657 Debris**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 5658 Debris



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources