

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1546 Entrance to location



Photo # 1558 Location

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1547 Location



Photo # 1548 Location

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1553 Location

Photo # 1554 Location

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024




Photo # 1555 Location

Photo # 1551 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1560 Lack of stabilization/compaction on location/insufficient BMP's

Photo # 1564 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1567 Lack of stabilization/compaction on location/insufficient BMP's



Photo # 1571 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1573 Lack of stabilization/Compaction/Insufficient tracking BMP's/Tracking from location onto lease road



Photo # 1543 Tracking on lease road/Insufficient tracking BMP's

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024




Photo # 1533 Tracking from lease road onto CR 306/Insufficient tracking BMP's



Photo # 1537 Tracking from lease road onto CR 306/Insufficient tracking BMP's

Inspection Photos

Location: QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad)

Location ID: 334064

Date: 12/30/2024



Photo # 1539 Tracking from lease road onto CR 306/Insufficient tracking BMP's



Photo # 1527 Tracking from lease road onto CR 306/Insufficient tracking BMP's