

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/30/2024

Submitted Date:

01/01/2025

Document Number:

707603475

FIELD INSPECTION FORM

Loc ID: 322723 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244142	WELL	SI	02/01/2023	OW	123-11935	OWL CREEK 9	PA

General Comment:

This is a PLUGGED & ABANDONED WELL inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Inactive | Shut-down.

Centralized Battery Formerly served 1 Location ID (322723).
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707603475 and/or Location ID #322723 for PA Well(s) info.
B.) Field Inspection Report doc. #707603477 and/or Location ID #322723 for Battery / Facility, Equipment info.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.522380,-104.597830

Comment:	Centralized Battery Formerly served 1 Location ID (322723). (Well(s): 1: Plugged & Abandoned PA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 244142 Type: WELL API Number: 123-11935 Status: SI Insp. Status: PA

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 12/30/2024 at approximately 13:22 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: OWL CREEK-67N64W/31SWSW Location ID: 322723 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 42 Start of Plugging Ops. Date: 11/06/2024. Approved. Form 42 MIRU on file. Date: 11/06/2024. Approved. Form 17 Bhd test: 11/07/2024. Approved. NOT cut/capped. Red PTA tag posted. Plugged & Abandoned PA well GPS coordinates: 40.523900 / -104.599200</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	01/01/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603476	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6860837