

Date: 12/30/2024



Photo # 1611 Location

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1580 Location



Photo # 1586 Location

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1610 Location



Photo # 1619 NW corner of location

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1620 SW corner of location



Photo # 1621 SE corner of location

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Dec 30, 2024 at 2:53:44 PM
+39.376451,-108.077964 ±3.37m
Parachute

Photo # 1622 NE corner of location



Dec 30, 2024 at 2:38:43 PM
+39.376664,-108.078453 ±4.01m
Parachute

Photo # 1599 Wildlife hazard

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1600 Wildlife hazard



Photo # 1601 Wildlife hazard

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1603 Wildlife hazard



Photo # 1624 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1626 Lack of stabilization/compaction on location/insufficient BMP's



Photo # 1628 Lack of stabilization/compaction on location/insufficient BMP's

Inspection Photos

Location: QB ENERGY HYRUP-68S96W/2NESW (Pad-2 K)

Location ID: 334342

Date: 12/30/2024



Photo # 1630 Lack of stabilization/compaction on location/insufficient BMP's



Photo # 1631 Lack of stabilization/compaction on location/insufficient BMP's