

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Photo 1 Location



Photo 2 Wellhead.

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Energy & Carbon Management Commission
40.10736, -104.83222, 4802.6ft, 99°
01/02/2025 14:10:40

Photo 3 Wellhead sign.



Energy & Carbon Management Commission
40.10743, -104.83216, 4807.4ft, 344°
01/02/2025 14:11:11

Photo 4 Ancillary equip.

Location ID: 318180



Photo 5 Tank battery.



Photo 6 Tank battery sign.

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Photo 7 Horizontal Heated Separator.



Photo 8 Gas meter run.

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Photo 9 Flow line manifold.



Photo 10 Unmarked flow lines.

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Photo 11 Flow line manifold.



Photo 12 Unmarked flow lines.

Inspection Photos
Location Name: R.S. Vincent unit 1
Location ID: 318180



Photo 13 Dead vegetation around the tank battery.



Photo 14 Leaking gear box.