

Inspection Photos

12/31/2024

Operator: ANSCHUTZ EXPLORATION CORP -
3104

Location ID: 484545

Inspection Doc: 718100142

Moffat County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



December 31, 2024



December 31, 2024

Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: **ANSCHUTZ EXPLORATION CORP - 3104**

Location ID: **484545**



Photo 3: Signage at Location entrance.

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 4: Photos taken from the stormwater diversion ditch on the southeast end of the Location. BMP has been filled and is no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 5: Photo shows equipment stored within the stormwater diversion ditch on the south end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 6: Photo taken from the south end of the Location. Photo shows sanitary facilities have not been physically secured. 4 facilities have been stored on the south end of the Location. These chemical containers have also been stored within 500 feet of an intermittent drainage.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 8: Photo taken from the south end of the Location. Photo shows stockpiled soils/materials missing BMPs to minimize erosion, degradation and sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 9: Photos 9-12 examples of trash/debris/rubbish observed improperly stored/placed on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 10: See comments under photo 9.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 11: See comments under photo 9.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 12: See comments under photo 9.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 13: Photos 13-15 examples showing containers (barrels, jugs, buckets, etc...) improperly stored on the location without proper spill prevention and containment measures. Photo 13 also shows open bucket containing what appears to be used filters and oil. This is not proper storage of chemicals or trash.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 14: See comments under photo 13.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 15: See comments under photo 13.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 16: Photos examples showing anchors on the Location. If anchors will be left permanently for future use (post drilling operations), anchor markers will need to comply with 1003.a and 603.j requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



December 31, 2024



December 31, 2024

Photo 17: Photos show a tank battery facility has been installed on the northeast end of the Location. Tanks have not been properly labelled pursuant to Rule 605.h. Photo right shows lines at tank have not been capped/plugged.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 18: Photos show lines at tanks on Location are missing cap/plug. Photos also show tanks/containers have not been properly labelled pursuant to Rule 605.h



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 19: See comments under photo 18.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 20: Photo taken from the topsoil stockpile on the northeast end of the Location. Photos show Operator has installed equipment on the topsoil stockpile. This does not comport with Rule 1002.c protection requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP - 3104

Location ID: 484545



Photo 21: Frac operations in process.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources