

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

01/03/2025

Document Number:

717300164**FIELD INSPECTION FORM**Loc ID 330983 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257501	WELL	SI	09/01/2020	GW	123-19985	HSR-MILLER FEDERAL 5-7A	PA
445907	LOCATION	AC			-	MILLER FD 5&6-7A O SA 34002746	EG

General Comment:ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 257501 Type: WELL API Number: 123-19985 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 445907 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (HSR Miller 5-7A); ECMC form 42 notice of start of plugging operations doc #403781163 received on 05/07/2024. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #403907799 received 09/03/2024 (FL's removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	01/03/2025
As outlined on ECMC form 19 spill report Doc #404032478 received on 12/19/2024: While conducting wellhead and flowline removal activities at the HSR-Miller Fed 5-7A Wellhead, historically impacted groundwater was discovered. The volume of the release is unknown. Assessment activities are ongoing. The wellhead and flowline are being permanently removed.	maclarej	01/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300168	Excavation/ remediation at facility battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6862793
717300169	PA well; view SE	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6862795