

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/03/2025

Submitted Date:

01/03/2025

Document Number:

710500408

FIELD INSPECTION FORM
 Loc ID 308588 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num:
Operator Information:

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275546	WELL	PR	02/01/2013	CBM	071-08284	BUSCH 42-30	EI
280338	PIT	AC			-	BUSCH 42-30 ONSITE	EI

General Comment:

This is a follow up Environmental Inspection for the Busch 42-30, well location located in Las Animas County CO.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Progressive Cavity	# 1				
Comment:		Hydraulic fitting leaking			
Corrective Action:		Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 01/24/2025	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 275546	Type: WELL	API Number: 071-08284	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280338	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
---------------------	-----------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
This is a follow up to Environmental Inspection 710500352, Original CAs corrected.	sanchezcc	01/03/2025
Hydraulic fitting leaking at wellhead.	sanchezcc	01/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500409	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6862929