

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/31/2024

Submitted Date:

01/03/2025

Document Number:

713400586

**FIELD INSPECTION FORM**

Loc ID 334545 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284850	WELL	PR	02/01/2015	GW	077-09073	MCDANIEL FEDERAL 2-14	PR
284851	WELL	PR	02/01/2015	GW	077-19074	MCDANIEL 2-11	PR
284852	WELL	PR	02/01/2015	GW	077-09072	MCDANIEL FEDERAL 2-13	PR
284853	WELL	PR	08/01/2017	GW	077-09071	MCDANIEL FEDERAL 2-12	PR
286126	WELL	PR	02/01/2015	GW	077-09121	MCDANIEL FEDERAL 11-3	PR
286127	WELL	PR	02/01/2015	GW	077-09120	MCDANIEL FEDERAL 11-4	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 12/31/2024 at approximately 13:30 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC McDaniel/2-11 Pad at Location ID #334545 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Housekeeping - Loose barbed wire fencing/wildlife hazard with a CA date 01/10/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	1-800-891-6191/911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Loose barbed wire fencing/wildlife hazard, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules		Date: 01/10/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Livestock panels		

Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	All Bradenhead valves are accessible with telemetry for monitoring		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284850	Type:	WELL	API Number:	077-09073	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284851	Type:	WELL	API Number:	077-19074	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284852	Type:	WELL	API Number:	077-09072	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	284853	Type:	WELL	API Number:	077-09071	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	286126	Type:	WELL	API Number:	077-09121	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	286127	Type:	WELL	API Number:	077-09120	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
		Compaction				
Compaction						
Berms						
		Berms				

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<span style="color: blue;">Please refer to Housekeeping for corrective action.</span>	popejoyd	01/03/2025
<span style="color: blue;">Limited storm water inspection due to snow cover</span>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400587	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863087">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863087</a>