

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2025

Submitted Date:

01/03/2025

Document Number:

707603503

FIELD INSPECTION FORMLoc ID 306506 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289305	WELL	PR	09/01/2024	OW	123-24805	STATE THOLEN 36-44	PR

General Comment:

This is a WELL inspection.
Well(s): 1: Producing | PR.
Battery: Active.

Centralized Battery serves 1 Location ID
(306506).
(Well(s): 1: Producing | PR).

Centralized Battery serves 1 Tank Battery Facility ID
(481875).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707603503 and/or Location ID #306506
for PR Well(s) info.
B.) Field Inspection Report doc. #707603506 and/or Facility ID #481875
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:	Wellsite(s): Propane. Placards		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Prime Mover: Gas engine. Protective shed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas engine drives hydraulic pump jack.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Assigned to Fac ID #481875.		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	Hydraulic pump jack.	
Corrective Action:		Date:
Type: Gas Meter Run	# 0	
Comment:	Assigned to Fac ID #481875.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 0	
Comment:	Assigned to Fac ID #481875.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.524062,-104.489049
Comment:	Centralized Battery serves 1 Location ID (306506). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (481875).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Assigned to Fac ID #481875.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Evins, Bret

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Assigned to Fac ID #481875.				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	CONCRETE SUMP/VAULT		40.524460,-104.490346
Comment:	Wellsite: Gas engine exhaust condensation vault.				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)	Gas engine exhaust condensation				
Other (Capacity)	2 Bbls.				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	289305	Type:	WELL	API Number:	123-24805	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	03/15/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 01/03/2025 at approximately 11:39 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: STATE THOLEN-67N64W/36SESE Location ID: 306506 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	01/03/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603504	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863155