

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/24/2024

Submitted Date:

12/28/2024

Document Number:

708905354

FIELD INSPECTION FORM

Loc ID 383328	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: 400390561
------------------	-----------------------------------	---	-----------------------

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

85 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301756	WELL	PR	04/16/2011	GW	045-18259	FEDERAL NER 433-32	PR
301757	WELL	PR	04/16/2011	GW	045-18260	FEDERAL RU 31-5	PR
301758	WELL	PR	04/16/2011	GW	045-18261	FEDERAL RU 32-5	PR
301759	WELL	PR	01/20/2015	GW	045-18262	FEDERAL NER 334-32	PR
430835	WELL	PR	12/02/2014	GW	045-21765	Federal NER 513-32	PR
430836	WELL	PR	12/06/2014	GW	045-21766	Federal NER 424-32	PR
430837	WELL	PR	04/01/2014	GW	045-21767	Federal RU 322-5	PR
430838	WELL	PR	04/14/2014	GW	045-21768	Federal RU 313-5	PR
430839	WELL	PR	02/12/2014	GW	045-21769	Federal RU 13-5	PR
430840	WELL	PR	03/01/2014	GW	045-21770	Federal RU 43-5	PR
430841	WELL	PR	02/12/2014	GW	045-21771	Federal RU 12-5	PR
430842	WELL	PR	03/01/2014	GW	045-21772	Federal RU 332-5	PR
430843	WELL	PR	06/24/2014	GW	045-21773	Federal RU 11-5	PR
430844	WELL	PR	08/12/2014	GW	045-21774	Federal NER 314-32	PR
430845	WELL	PR	08/12/2014	GW	045-21775	Federal NER 443-32	PR
430846	WELL	PR	12/07/2014	GW	045-21776	Federal NER 523-32	PR
430848	WELL	PR	12/01/2017	GW	045-21777	Federal RU 21-5	PR
430849	WELL	PR	07/01/2024	GW	045-21778	Federal NER 434-32	PR
430850	WELL	PR	05/10/2014	GW	045-21779	Federal NER 344-32	PR
430851	WELL	PR	08/12/2014	GW	045-21780	Federal NER 414-32	PR

430852	WELL	PR	03/25/2014	GW	045-21781	Federal RU 311-5	PR
430853	WELL	PR	03/24/2014	GW	045-21782	Federal RU 41-5	PR
430854	WELL	PR	10/13/2014	GW	045-21783	Federal NER 534-32	PR
430855	WELL	PR	11/29/2014	GW	045-21784	Federal NER 34-32	PR
430856	WELL	PR	06/24/2014	GW	045-21785	Federal NER 444-32	PR
430857	WELL	PR	05/10/2014	GW	045-21786	Federal NER 514-32	PR
430858	WELL	PR	11/30/2014	GW	045-21787	Federal NER 413-32	PR
430860	WELL	PR	02/12/2014	GW	045-21788	Federal RU 331-5	PR
430861	WELL	PR	12/05/2014	GW	045-21789	Federal NER 423-32	PR
430862	WELL	PR	06/24/2014	GW	045-21790	Federal NER 44-32	PR
430863	WELL	PR	10/13/2014	GW	045-21791	Federal NER 343-32	PR
430864	WELL	PR	11/09/2014	GW	045-21792	Federal NER 324-32	PR
430865	WELL	PR	10/13/2014	GW	045-21793	Federal NER 14-32	PR
430866	WELL	PR	03/01/2014	GW	045-21794	Federal RU 22-5	PR
430867	WELL	PR	01/19/2014	GW	045-21795	Federal RU 341-5	PR
430868	WELL	PR	12/01/2014	GW	045-21796	Federal NER 533-32	PR
430869	WELL	PR	12/06/2014	GW	045-21797	Federal NER 24-32	PR
430870	WELL	PR	10/01/2014	GW	045-21798	Federal NER 524-32	PR
430871	WELL	PR	01/18/2014	GW	045-21799	Federal RU 321-5	PR
430872	WELL	PR	01/19/2014	GW	045-21800	Federal RU 42-5	PR

General Comment:[CECMC Inspection Report Summary](#)

On 12/24/2024 at approximately 12:38 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad.
 Location # 383328 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear Habitat areas.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Open ended load line with a CA date of 01/04/2025

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign weathered & illegible/does not comply with CECMC rules - please refer to photo log		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Multiple wellhead signs weathered & starting to become illegible		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Small amount of staining in 2 areas - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Qnergy nat gas gen set, Qnergy air compressor, catalytic heater & thermogens - hog panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Methanol tank - hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Catalytic heater		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Equipment not listed in FORM 2A or FORM 4 SUNDRY		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Qnergy nat gas gen set, Qnergy air compressor, chemical tanks, Summit Midstream meter house, pig station & other equipment on location are not listed in operators FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules.		
	If operator remains out of compliance corrective actions may be issued in future inspections.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Thermogens		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Qnergy natural gas generator		
	Equipment not listed in FORM 2A or FORM 4 SUNDRY		
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Qnergy air compressor		
	Equipment not listed in FORM 2A or FORM 4 SUNDRY		
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 20		
Comment:	Pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible.		
	FEDERAL NER 334-32 bradenhead line connected to flowline - FORM 4 SUNDRY document # 402542942		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		

Comment:	Chemical tanks Equipment not listed in FORM 2A or FORM 4 SUNDRY			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Summit Midstream Equipment not listed in FORM 2A or FORM 4 SUNDRY			
Corrective Action:			Date:	
Type: Bradenhead	# 20			
Comment:	Pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Open ended load line			
Corrective Action:	All load lines will be capped or plugged		Date:	01/04/2025
Type: Gas Meter Run	# 20			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	In centralized containment with the 3 condensate tanks			
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Centralized containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment: Equipment not listed in FORM 2A or FORM 4 SUNDRY						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 500 gal						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Separate containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment: Tanks equipped with telemetry						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment: Centralized containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	6	300 BBLs	STEEL AST		,	
Comment: 2 of the 6 tanks are equipped with telemetry						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities						
Facility ID:	301756	Type:	WELL	API Number: 045-18259	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	301757	Type:	WELL	API Number: 045-18260	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	301758	Type:	WELL	API Number: 045-18261	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	301759	Type:	WELL	API Number: 045-18262	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	430835	Type:	WELL	API Number: 045-21765	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	430836	Type:	WELL	API Number: 045-21766	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	430837	Type:	WELL	API Number: 045-21767	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	430838	Type:	WELL	API Number: 045-21768	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430839	Type:	WELL	API Number: 045-21769 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430840	Type:	WELL	API Number: 045-21770 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430841	Type:	WELL	API Number: 045-21771 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430842	Type:	WELL	API Number: 045-21772 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430843	Type:	WELL	API Number: 045-21773 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430844	Type:	WELL	API Number: 045-21774 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	430845	Type:	WELL	API Number: 045-21775 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430846	Type:	WELL
API Number:	045-21776	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430848	Type:	WELL
API Number:	045-21777	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430849	Type:	WELL
API Number:	045-21778	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430850	Type:	WELL
API Number:	045-21779	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430851	Type:	WELL
API Number:	045-21780	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430852	Type:	WELL
API Number:	045-21781	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430853	Type:	WELL
API Number:	045-21782	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID: 430854	Type: WELL	API Number: 045-21783	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430855	Type: WELL	API Number: 045-21784	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430856	Type: WELL	API Number: 045-21785	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430857	Type: WELL	API Number: 045-21786	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430858	Type: WELL	API Number: 045-21787	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430860	Type: WELL	API Number: 045-21788	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430861	Type: WELL	API Number: 045-21789	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 430862	Type: WELL	API Number: 045-21790	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430863	Type:	WELL
API Number:	045-21791	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430864	Type:	WELL
API Number:	045-21792	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430865	Type:	WELL
API Number:	045-21793	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430866	Type:	WELL
API Number:	045-21794	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430867	Type:	WELL
API Number:	045-21795	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430868	Type:	WELL
API Number:	045-21796	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	430869	Type:	WELL
API Number:	045-21797	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing, well on plunger lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	430870	Type:	WELL	API Number:	045-21798	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	430871	Type:	WELL	API Number:	045-21799	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	430872	Type:	WELL	API Number:	045-21800	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:				Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
		Gravel				Sparse to none in sections
Ditches						
Retention Ponds						
		Ditches				
Gravel						Sparse to none in some visible areas
Compaction						
		Culverts				
		Compaction				Small amount of light compaction in some sections
				Material Handling And Spill Prevention		Chemical tank containments

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective action & also refer to Signs/Marker, Housekeeping & Equipment for comments.	smelserw	12/28/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404042296	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855841
708905355	Inspection 708905354 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855839
708905356	Inspection 708905354 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855840