

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2024

Submitted Date:

12/30/2024

Document Number:

708700077

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
 Name of Operator: SIMCOE LLC  
 Address: 1199 MAIN AVE SUITE 101  
 City: DURANGO State: CO Zip: 81301

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
, SIMCOE		sjninspections@ikavenergy.co	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488909	SPILL OR RELEASE	AC	12/30/2024		-	State CF1 - Dry Creek	EI

**General Comment:**

This is an environmental inspection to document status of spill. See attached photos.

Spill reported to area Environmental Protection Specialist Jason Kosola via phone call on 12/20/2024. Spill of produced water from pipeline appears to be a long term, ongoing release into Dry Creek which is considered Waters of the State.

**Inspected Facilities**

Facility ID: 488909 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Spill of produced water from pipeline was reported via phone call on 12/20/2024. Spill appears to be a long term release occurring since at least 9/17/2024 as shown on the attached aerial photos. Multiple domestic water wells are present downstream from where release entered Dry Creek.

Corrective Action: Operator shall send spill notification to owners of domestic water wells that meet the following criteria: a screened interval less than or equal to 80 feet below ground surface, wellbore located within 200 feet of the banks of Dry Creek, and wellbore located within 1 mile downstream from where spill entered Dry Creek.

Date: 01/20/2025

Reportable: YES GPS: Lat 37.214951 Long -107.649598

Proximity to Surface Water: 0 Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404043571	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857569">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857569</a>
708700078	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857549">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857549</a>
708700079	Google earth image	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857550">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857550</a>
708700080	Google earth image map	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857551">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857551</a>