

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/23/2024

Submitted Date:

12/30/2024

Document Number:

717000234**FIELD INSPECTION FORM**Loc ID 320062 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
, COGCC		conor.pesicka@state.co.us	
Supervisor, ECME		jason.gomez@state.co.us	
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202467	WELL	PR	05/01/2024	GW	001-07872	UPRR 23 PAN AM M 3	SI

General Comment:[Follow-up inspection DOC# 717000078 / No equipment has been changed](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds throughout location		
Corrective Action:	Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 1/10/2025 . See attached all photos	Date:	01/10/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Flow lines for the separator are not LOTO/and are unmarked.		
Corrective Action:	• Rule 1102.g.: Flowline risers not LO/TO or marked are considered unused equipment. Comply with Rule 1102.g. For unused, unmarked flow line risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 1/31/2025. See attached photo # 5, 6 & 7.	Date:	01/31/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 202467 Type: WELL API Number: 001-07872 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 05/09/2024 Annual Brhd Completed? _____Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: Appeared to be plumbed to the surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary</p> <p>On Monday December 13:45pm 23rd at approximately (). I, Inspector Chane Finkenbinder, conducted an on-site follow-up inspection.</p> <p>This is a follow up inspection from DOC# 717000078. No actions were taken to correct the corrective actions from DOC# 717000078.</p> <p>Operator: KP KAUFMANN</p> <p>Location name: UPRR 23 PAN AM M3</p> <p>API # 001-07872</p> <p>Location ID #: 320062</p> <p>County: Adams</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 606: Weeds, dead weeds, trash, debris & unnecessary / unused equipment. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date. See attached all photos 1/10/2025</p> <p>Rule 1102.g.: Flowline risers not LO/TO or marked are considered unused equipment. Comply with Rule 1102.g. For unused, unmarked flow line risers 24 hrs. To lock out tag out. 30 days to remove riser. Corrective Action Date 30 days. See attached photo # 4,5 & 6</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	12/30/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404043617	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857605
717000235	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857602