

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

01/02/2025

Document Number:

707603485**FIELD INSPECTION FORM**Loc ID 332163 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270653	WELL	PA	04/06/2022	GW	123-21921	UYEMURA 34-31	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Inactive | Shut-down.

Centralized Battery Formerly served 4 Location IDs  
(332163, 305099, 305156, 332495).  
(Well(s): 4: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(488831).  
Centralized Battery SE corner GPS coordinates: 40.523601 / -104.588834

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707603485 and/or Location ID #332163  
for PA Well(s) info.  
B.) Field Inspection Report doc. #707603487 and/or Location ID #305099  
for PA Well(s) info.  
C.) Field Inspection Report doc. #707603489 and/or Location ID #305156  
for PA Well(s) info.  
D.) Field Inspection Report doc. #707603491 and/or Location ID #332495  
for PA Well(s) info.  
E.) Field Inspection Report doc. #707603493 and/or Facility ID #488831  
for Battery / Facility, Equipment info.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 0		
Comment:	Equipment assigned to Fac ID #488831.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Equipment assigned to Fac ID #488831.		
Corrective Action:			Date:
Type: Compressor	# 0		
Comment:	Equipment removed.		
Corrective Action:			Date:
Type: Ancillary equipment	# 0		
Comment:	Equipment assigned to Fac ID #488831.		
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:	Equipment assigned to Fac ID #488831.		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Equipment assigned to Fac ID #488831.				
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>

Other (Type)						
<u>Berms</u>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type		Tank ID	SE GPS
PRODUCED WATER	0					
Comment: Equipment assigned to Fac ID #488831.						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 270653 Type: WELL API Number: 123-21921 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On MON 12/30/2024 at approximately 15:09 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: UYEMURA-67N64W/31SWSE Location ID: 332163 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Inactive   Shut-down.</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 04/06/2022. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.523780 / -104.590640</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	01/02/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603486	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6861410">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6861410</a>