

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

01/02/2025

Document Number:

707603487**FIELD INSPECTION FORM**Loc ID 305099 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274144	WELL	SI	12/01/2022	OW	123-22441	UYEMURA 33-31	PA

General Comment:This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Inactive | Shut-down.

Centralized Battery Formerly served 4 Location IDs

(332163, 305099, 305156, 332495).

(Well(s): 4: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(488831).

Centralized Battery SE corner GPS coordinates: 40.523601 / -104.588834

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707603485 and/or Location ID #332163
for PA Well(s) info.B.) Field Inspection Report doc. #707603487 and/or Location ID #305099
for PA Well(s) info.C.) Field Inspection Report doc. #707603489 and/or Location ID #305156
for PA Well(s) info.D.) Field Inspection Report doc. #707603491 and/or Location ID #332495
for PA Well(s) info.E.) Field Inspection Report doc. #707603493 and/or Facility ID #488831
for Battery / Facility, Equipment info.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type:			corrective date
Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:
Ancillary equipment	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 274144 Type: WELL API Number: 123-22441 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 12/30/2024 at approximately 15:13 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: UYEMURA-67N64W/31NWSE Location ID: 305099 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 11/06/2024. Approval Pending. Plugged & Abandoned PA well GPS coordinates: 40.527140 / -104.590560</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	01/02/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603488	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6861411