

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2025

Submitted Date:

01/06/2025

Document Number:

715800494

FIELD INSPECTION FORM

Loc ID 318207 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240872	WELL	PR	04/27/1976	OW	123-08660	DITLEV-SIMONSEN C 1	SI

General Comment:

[This is a follow up wellsite audit/inspection](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Excavation stock pile/debris sits to the east of the wellsite set on plastic liner that is starting to disintegrate & needs to be removed.		
Corrective Action:	Install/repair required BMPs per Rule 1002.f.(2)C		Date: 05/31/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Shares fence with the WH, Angle iron.		
Corrective Action:			Date:
Type	OTHER		
Comment:	The open pipeline excavation has Temp. orange construction fence.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box & transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240872 Type: WELL API Number: 123-08660 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI valves are closed & electric panel is shut off.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary. On Monday 1-6-2025 at approximately 1450 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR doc # 716400148 Operator: KP Kauffman Location ID # 318207 Well Name: Ditlev-Simonsen C1 API # 05-123-08660 County: Weld Weather: Cloudy & cold Location: Dry Temperature: 36* While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues have been addressed: 605.g Signs Gen. Cond: has been addressed. 913.B.i fence or cover open excavations: has been addressed. During this inspection, I observed the following possible compliance issues have not been addressed: 1002.f.(2)C: CA date 5-31-2024. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules. Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	01/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800495	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865642