

# Final Reclamation and Stormwater Inspection

Date: 01/02/2025

Operator: STELBAR OIL CORP INC - 82470

Location ID: 317263

Inspection Document #: 708201890

Washington County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 1.** Taken from the start of the access road, west of the location. Portions of the former access road appear to be progressing towards reclamation standards and regulations.





**Photo 2.** Photo taken from the southwest corner of the former location. Undesirable vegetation (russian thistle, kochia) was observed throughout the disturbance areas. Additional reclamation activities are required to establish desirable perennial vegetation that is reflective of the adjacent reference areas.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 3.** Photo taken from the southeast corner of the former location. See comments in Photo 2 for additional information.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 4.** Photo taken from the northeast corner of the former location. See comments in Photo 2 for additional information.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 5.** Photo taken from the northwest corner of the former location. See comments in Photo 2 for additional information.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 6.** Access road Photo taken west of the location. Photo illustrates that portions of the access road do not appear to have been recontoured/graded to match the adjacent topography with ruts evident.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 7.** Continued from Photo 6; see comments in previous photo.



Inspection Photos  
Location Name: Young 2-35  
Location ID: 317263



**Photo 8.** Reference area photo taken northwest of the former location.