

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2024

Submitted Date:

01/06/2025

Document Number:

708303268**FIELD INSPECTION FORM**Loc ID 335277 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Smelser, Wayne		wayne.smelser@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211446	WELL	PR	05/20/2015	GW	045-07206	GIBSON GULCH UNIT 13-30	PR
268445	WELL	PR	09/06/2003	GW	045-09259	GIBSON GLCH UNIT 12-30	PR
270374	WELL	PR	04/26/2005	GW	045-09540	GIBSON GULCH UNIT 12-30 D	PR

**General Comment:****CECMC Inspection Report Summary**

On 12/31/2024 at approximately 13:50, Compliance Inspector Matthew Morris conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30SSW at Location ID #335277 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Dead weeds accumulating around wellheads
- 2) Stored supplies in tank containment (load hose/fire hose)
- 3) Unused equipment; storage tank is not in service
- 4) Wildlife entry hazard at separators
- 5) Open-ended line on fresh water tank poses a wildlife entry hazard

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Fresh water tank is not plumbed in and is not in service.		
Corrective Action:	Remove unused equipment to comply with Rule 606.	Date:	02/06/2025
Type	WEEDS		
Comment:	Weeds accumulating around wellheads.		
Corrective Action:	Remove weeds from location to comply with Rule 606.	Date:	01/14/2025
Type	STORAGE OF SUPL		
Comment:	Load hose/fire hose stored in tank containment.		
Corrective Action:	Remove stored supplies to comply with Rule 606.	Date:	01/14/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:	Wildlife entry hazards at separators.		
Corrective Action:	Secure equipment to prevent wildlife entry.	Date:	01/12/2025
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLs	STEEL AST		,	
Comment:	Open-ended load line poses a wildlife entry hazard. Tank is not in service.					
Corrective Action:	Secure equipment to prevent wildlife entry.					Date: 01/12/2025

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211446	Type:	WELL	API Number:	045-07206	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	268445	Type:	WELL	API Number:	045-09259	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	270374	Type:	WELL	API Number:	045-09540	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
		Culverts				
Compaction						
Gravel						
		Compaction				
		Ditches				

Comment: Location surface is frozen. Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303269	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865800">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865800</a>