

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 6488 From entrance to location




Photo # 6489 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 6490 Location



Photo # 6491 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad**  
**Location ID: 449385**



**Photo # 6492 Location**



**Photo # 6493 Location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 6494 Location



Photo # 6495 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



Photo # 6496 Location



Photo # 6497 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad

Location ID: 449385



**Photo # 6498 Location**



**Photo # 6499 Secondary containment liner showing signs of damage/disrepair near top of metal containment ring**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC WARE SR 23-12 Pad**

**Location ID: 449385**



**Photo # 6500 Secondary containment liner showing signs of damage/disrepair near top of metal containment ring**