

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

12/31/2024

Document Number:

708905369**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Smelser, Wayne 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Morris, Matthew		matthew.morris@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414557	PIT	AC			-	33-1-795	AC

**General Comment:****CECMC Inspection Report Summary**

On 12/30/2024 at approximately 11:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC 33-1-795 Pit.

Facility ID: 414557 in Garfield County Colorado.

Please refer to inspection 708903976 conducted on 06/05/2024, 3 of 4 previous corrective actions have been completed.

Open ended load line corrective action has not been completed &amp; CA date remains 06/12/2024

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Multiple open ended piping/wildlife hazards/available for entry by wildlife with a CA date of 01/07/2025
2. Equipment - Open ended load line with a CA date of 06/12/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	No tank battery on location			
Corrective Action:				Date:
Type	OTHER			
Comment:	Sign on pit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PIT			
Comment:	Metal posts & netting			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Barbed wire fence			
	Fencing showing some signs of disrepair & could constitute a wildlife hazard (Western side of location)			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Other	# 2			corrective date
Comment:	Open ended piping/wildlife hazards/available for entry by wildlife			
	Netting near piping also needs maintenace			
Corrective Action:	Comply with CECMC wildlife rules			Date: 01/07/2025

Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged		Date: 06/12/2024
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	414557	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Gravel						Sparse to none in areas
		Compaction				Light compaction in some sections
		Ditches				
Berms						
Compaction						Small amount of light compaction
		Gravel				Sparse to none in visible areas

Comment: [Some signs of lack of stabilization & sloughing on cut slope \(N/NE area of location\)](#)[Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for corrective actions &amp; also refer to Housekeeping, Fencing &amp; Stormwater for comments.</a>	smelserw	12/31/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404045167	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859725">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859725</a>
708905370	Inspection 708905369 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859719">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859719</a>
708905371	Inspection 708905369 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859720">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6859720</a>