

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 01/07/2025 Document Number: 403711814

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 46290 Contact Person: Mani Silva Company Name: KP KAUFFMAN COMPANY INC Phone: (303) 8254822 Address: 1700 LINCOLN ST STE 4550 Email: regulatory@kpk.com City: DENVER State: CO Zip: 80203 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 444947 Location Type: Production Facilities Name: North Quebec TB Number: County: ADAMS Qtr Qtr: NESE Section: 8 Township: 1S Range: 67W Meridian: 6 Latitude: 39.976330 Longitude: -104.903480

Description of Corrosion Protection

Carbon Steel pipelines are typically covered with a protective external coating, and are subject to rigorous fabrication, inspection, and quality control standards to reduce the occurrence of pipe and coating defects that can lead to external corrosion. While the likelihood of corrosion is minimal due to low operating pressures, KPK regularly inspects and pressure tests all lines to ensure corrosion is not occurring.

Description of Integrity Management Program

Production and upkeep of KPK's assets involves regular hands-on operation by KPK's field crews. These field crews not only maintain safe production, but also conduct routine inspections to confirm proper integrity of the production systems. While pipeline integrity issues are minimal due to pipeline materials and low operating pressure, KPK regularly inspects and pressure tests all lines to ensure pipeline integrity is maintained.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Construction of pipelines is generally not occurring. When necessary to remedy a pipeline issue, KPK typically assesses all conditions to determine the proper construction method. A combination of boring and open trench are utilized by KPK.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 476097 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 335735 Location Type: Well Site   
Name: TALON POINT Number: 15-8  
County: ADAMS No Location ID  
Qtr Qtr: SWSE Section: 8 Township: 1S Range: 67W Meridian: 6  
Latitude: 39.974361 Longitude: -104.908833

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 03/10/2008  
Maximum Anticipated Operating Pressure (PSI): Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 03/06/2024

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
Municipality		Thornton
County	ADAMS	N/A

**Description of Abandonment Verification:**

The flowline has been abandoned.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 476098 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 320484 Location Type: Well Site   
Name: NORTH QUEBEC-61S67W Number: 8NESE  
County: ADAMS No Location ID  
Qtr Qtr: NESE Section: 8 Township: 1S Range: 67W Meridian: 6  
Latitude: 39.977869 Longitude: -104.905642

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 10/02/2001

Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_

Testing PSI: \_\_\_\_\_

Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 03/06/2024

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
Municipality		Thornton
County	ADAMS	N/A

**Description of Abandonment Verification:**

The flowline has been abandoned.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 476099 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 319670 Location Type: Well Site

Name: N QUEBEC-61S67W Number: 8NWSE

County: ADAMS No Location ID

Qtr Qtr: NWSE Section: 8 Township: 1S Range: 67W Meridian: 6

Latitude: 39.977319 Longitude: -104.910352

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 01/21/1976

Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_

Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 03/06/2024

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

Jurisdiction	County	Municipality
County	ADAMS	N/A
Municipality		Thornton

**Description of Abandonment Verification:**

The flowline has been abandoned.

## OPERATOR COMMENTS AND SUBMITTAL

Comments

This form is being submitted to acknowledge that all 3 flowlines from the now abandoned well to the now abandoned facilities have been removed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 01/07/2025 Email: tjkilian@kpk.com

Print Name: TJ Kilian Title: Field Engineer

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:



**Director of ECMC**

Date: 1/7/2025

**CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

--	--

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

403711814	Form44 Submitted
403711991	OFF-LOCATION FLOWLINE GIS KML
404050350	ABANDONMENT IN PLACE DOCUMENTATION

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

Engineer	Attached correspondence with KPK to affirm all three lines were removed.	01/07/2025
----------	--	------------

Total: 1 comment(s)