

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2025

Submitted Date:

01/07/2025

Document Number:

714201990

**FIELD INSPECTION FORM**

Loc ID 474767	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> <div style="border: 1px solid black; padding: 2px;"> 42    Number of Comments  0    Number of Corrective Actions  <input type="checkbox"/> Corrective Action Response Requested </div>
<b>Operator Information:</b> ECMC Operator Number: 10651 Name of Operator: VERDAD RESOURCES LLC Address: 1125 17TH STREET SUITE 550 City: DENVER    State: CO    Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477665	WELL	PR	04/01/2024	OW	123-51164	County Line 3130-04H	PR
477667	WELL	PR	08/16/2022	OW	123-51166	County Line 3107-05H	PR
477668	WELL	PR	09/04/2022	OW	123-51167	County Line 3107-09H	PR
477669	WELL	PR	08/14/2022	OW	123-51168	County Line 3112-03H	PR
477670	WELL	PR	04/01/2024	OW	123-51169	County Line 3130-01H	PR
477671	WELL	PR	04/01/2024	OW	123-51170	County Line 3107-11H	PR
477672	WELL	PR	08/26/2022	OW	123-51171	County Line 3112-01H	PR
477673	WELL	PR	08/09/2022	OW	123-51172	County Line 3107-06H	PR
477674	WELL	PR	09/03/2022	OW	123-51173	County Line 3107-08H	PR
477675	WELL	PR	04/01/2024	OW	123-51174	County Line 3107-12H	PR
477676	WELL	PR	04/01/2024	OW	123-51175	County Line 3107-10H	PR
477677	WELL	PR	04/01/2024	OW	123-51176	County Line 3130-06H	PR
477678	WELL	PR	04/01/2024	OW	123-51177	County Line 3130-05H	PR
477679	WELL	PR	08/28/2022	OW	123-51178	County Line 3112-02H	PR
477680	WELL	PR	08/14/2022	OW	123-51179	County Line 3107-07H	PR
477681	WELL	PR	04/01/2024	OW	123-51180	County Line 3130-02H	PR
477682	WELL	PR	08/14/2022	OW	123-51181	County Line 3112-04H	PR
481258	WELL	PR	08/01/2024	OW	123-51638	COUNTYLINE 0508-13H	PR
481259	WELL	PR	08/01/2024	OW	123-51639	COUNTYLINE 0508-16H	PR
481260	WELL	PR	08/01/2024	OW	123-51640	COUNTYLINE 0508-14H	PR
481261	WELL	PR	08/01/2024	OW	123-51641	COUNTYLINE 0508-17H	PR
481262	WELL	PR	08/01/2024	OW	123-51642	COUNTYLINE 0508-15H	PR

483977	WELL	PR	07/01/2024	OW	123-52049	County Line 3229-18H	PR
483978	WELL	PR	07/01/2024	OW	123-52050	County Line 3229-19H	PR
483979	WELL	PR	07/01/2024	OW	123-52051	County Line 3229-20H	PR
483980	WELL	PR	07/01/2024	OW	123-52052	County Line 3229-21H	PR
483981	WELL	PR	07/01/2024	OW	123-52053	County Line 3229-22H	PR
483982	WELL	PR	07/01/2024	OW	123-52054	County Line 3229-23H	PR
483983	WELL	PR	07/01/2024	OW	123-52055	County Line 3229-24H	PR
483984	WELL	PR	07/01/2024	OW	123-52056	County Line 3229-25H	PR
483985	WELL	PR	07/01/2024	OW	123-52057	County Line 3229-26H	PR

**General Comment:**

This is an audit of COUNTY LINE PAD scout card and related documents followed by a field inspection.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	#		
Comment:	31 total		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		

Comment: 31 total			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity) 538 BBLS	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with other tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity) 538 BBLS	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:



Inspected Facilities			
Facility ID: 477665	Type: WELL	API Number: 123-51164	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0      Fluid Type:	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 477667	Type: WELL	API Number: 123-51166	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 20      Fluid Type:	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 477668	Type: WELL	API Number: 123-51167	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 2      Fluid Type:	
End Surf Csg Pressure: 0			
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 477669	Type: WELL	API Number: 123-51168	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	

<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 19	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477670	Type: WELL	API Number: 123-51169	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<b>Producing Well</b>	
Comment: PR; valves appear to be in the open position.	
Corrective Action:	Date:

<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 5	Fluid Type:
		End Surf Csg Pressure: 0	
Comment: PR; valves appear to be in the open position.			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477671	Type: WELL	API Number: 123-51170	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<b>Producing Well</b>	
Comment: PR; valves appear to be in the open position.	
Corrective Action:	Date:

<b>BradenHead</b>			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477672	Type: WELL	API Number: 123-51171	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

<b>Producing Well</b>	
Comment: PR; valves appear to be in the open position.	
Corrective Action:	Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477673 Type: WELL API Number: 123-51172 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 33 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477674 Type: WELL API Number: 123-51173 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477675 Type: WELL API Number: 123-51174 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:



**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 19 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477676 Type: WELL API Number: 123-51175 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 30 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477677 Type: WELL API Number: 123-51176 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477678 Type: WELL API Number: 123-51177 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477679 Type: WELL API Number: 123-51178 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477680 Type: WELL API Number: 123-51179 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477681 Type: WELL API Number: 123-51180 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 11 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 477682 Type: WELL API Number: 123-51181 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481258 Type: WELL API Number: 123-51638 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 35 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481259 Type: WELL API Number: 123-51639 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481260 Type: WELL API Number: 123-51640 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481261 Type: WELL API Number: 123-51641 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 48 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 481262 Type: WELL API Number: 123-51642 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 20 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483977 Type: WELL API Number: 123-52049 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483978 Type: WELL API Number: 123-52050 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483979 Type: WELL API Number: 123-52051 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483980 Type: WELL API Number: 123-52052 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483981 Type: WELL API Number: 123-52053 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483982 Type: WELL API Number: 123-52054 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483983 Type: WELL API Number: 123-52055 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483984 Type: WELL API Number: 123-52056 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/25/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 483985 Type: WELL API Number: 123-52057 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

BradenHead			
Date of Last Brhd Test: 09/25/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure: 22	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel		Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<a href="#">Routine inspection. Weather conditions: cloudy.</a>	santistb	01/07/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201994	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6866975">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6866975</a>