

Inspection Photos

Loc: 322234

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/6/2025

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. The access road has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 1/6/2025

Inspection Photos



Photo 2. Facing south toward the location. The well has been plugged and abandoned however final reclamation has not been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 1/6/2025

Inspection Photos



Photo 3. Facing southwest along the fill slope. The location will need to be recontoured back to the original slopes



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 1/6/2025

Inspection Photos



Photo 4. The electric utilities remain at the location and should have been removed with 3 months of abandonment. The entire powerline and poles servicing this location must be removed. There is a topsoil pile shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 1/6/2025

Inspection Photos



Photo 5. Facing toward the south side of the location where tank battery was located.



Inspection Photos



Photo 6. Facing southwest at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.



Inspection Photos



Photo 7. Facing toward the cut slope. There are riling erosion along the cut slope which is not stabilized. Previous CA was not completed.



Inspection Photos



Photo 8. Facing northwest along the cut slope. There cut slope is not stabilized.



Inspection Photos



Photo 9. Facing south at the location standing from base of the cut slope.

