

Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 1/6/2025



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the drainage crossing which has been washed out and has not been repaired. Previous corrective action was not completed.



Inspection Photos



Photo 2. View of culvert outlet shows displaced rock. Outlet protection will need to be reinstalled. Previous corrective action was not completed.



Inspection Photos



Photo 3. Facing southwest toward the wellsite. There are undesirable weeds around the equipment that need to be controlled. There are two new tanks brought to the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 1/6/2025

Inspection Photos



Photo 4. Facing southwest toward the interim reclamation area. The perennial vegetation has not established and this area has not been reseeded. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 1/6/2025

Inspection Photos



Photo 5. Facing northwest toward the interim reclamation area. The perennial vegetation has not established. This area will need weed control and reseeding. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 1/6/2025

Inspection Photos



Photo 6. There has been two steel tanks brought into the location. Secondary containment must be installed per rule 603.o. which requires impervious liner and containment.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 1/6/2025