

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2025

Submitted Date:

01/07/2025

Document Number:

693807958**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Gomez, Jason		jason.gomez@state.co.us	
Nowak, Scott	(713) 600-6221	scottn@paradoxresources.co m	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269202	GAS PROCESSING PLANT	AC	02/13/2002		-	ANDY'S MESA GAS PLANT 269202	IO

General Comment:

FLIR Inspection for Andy's Mesa Gas Plant.
Facility Closed with gate locked. No active operations.
See inspection text and photos for details.

LocationOverall Good: ☒**Signs/Marker:**

Type OTHER

Comment: Facility entrance sign displays "GNG Andy's Mesa Compressor Station". COGIS system lists Paradox Upstream LLC (10453) as operator. COGIS search for GNG (GREEN NATURAL GAS VENTURES LLC - 10845) shows 0 facilities in San Miquel county owned by this operator. COGIS search for (AMERICAN HELIUM OPERATING LLC) shows 0 facilities in San Miquel county owned by this operator. No Form 9 (Transfer of Operatorship) on file. No Form 12 (Gas Facility Registration/Change of Operator) on file.

Corrective Action: Required reports not filed. Submit reports as per Rule 207.

Date: 02/07/2025

Emergency Contact Number:

Comment: 435-686-2271

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER					38.046444,-108.637245

Comment: Tank Battery #3 (See Inspection photos)
Tank 4/5 full as viewed thru FLIR Camera. Contents unknown.

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	300 BBLs	HEATED STEEL AST		38.045866,-108.637055

Comment: Tank Battery #2 (See Inspection photos)
Tank 3/4 full as viewed thru FLIR Camera. Contents unknown.

Corrective Action:

Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		38.044984,-108.637541
Comment:	Tank Battery #1 (See Inspection photos) N tank 1/2 full, S tank 1/4 full as viewed thru FLIR Camera.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	269202	Type:	GAS	API Number:	-	Status:	AC	Insp. Status:	IO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 38.045321 Long: -108.638643Wind: Calm Speed: 0 (mph) Direction From: _____ Weather: Cloudy Temperature: 30 (F)Assisting Staff: _____ Camera #: 2☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:00	AM	11:30	AM	Water Tank(s)

Comment: 2 of 4 Storage tanks near capacity.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807959	FLIR Inspection photos 1/7/2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6867787