

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

01/01/2025

Document Number:

713400574**FIELD INSPECTION FORM**Loc ID 334064 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281947	WELL	SI	11/01/2021	GW	045-11591	KNOX 11-5 (OD11)	SI

General Comment:CECMC Inspection Report Summary

On 12/30/2024 at approximately 12:06 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection for a Plugging Operation at QB ENERGY KNOX-68S96W/11NWNW (OD11 Pad) at Location ID #334064 in Garfield County, Colorado.

While there, I observed plugging crew pressure testing BH on Knox 11-5 well.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Stormwater - Lack of stabilization/compaction on location/insufficient tracking BMP's & Vehicle tracking onto lease road & CR 306/Insufficient tracking BMP's with a CA of 01/16/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615/911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Workover Rig and all associated equipment		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement tank		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Well heater		
Corrective Action:		Date:	

Type: Other	# 2		
Comment:	Frac tanks		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	281947	Type:	WELL	API Number:	045-11591	Status:	SI	Insp. Status:	SI
Cement									
Cement Contractor									
Contractor Name: JMR					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range):					Cement Volume (sx):				
Good Return During Job:					Cement Type:				
<div>Comment: 12/30/2024 at approximately 12:15 I observed plugging crew pressure testing BH on Knox 11-5 well. Please refer to document numbers 404024463 & 404024491 Last produced October 2021</div>									
Corrective Action:							Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Fail	Tracking onto lease road & CR 306
		Ditches				
Compaction	Fail					Lack of stabilization/compaction
		Culverts				
Berms						
		Compaction				
		Gravel				Sparse

Comment: 1. Lack of stabilization/compaction on location/insufficient tracking BMP's

2. Vehicle tracking onto lease road & CR 306/Insufficient tracking BMP's

Corrective Action: **Comply with CECMC Storm water rules**

Date: 01/16/2025

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Stormwater for corrective action.	popejoyd	01/01/2025
Limited inspection due to ongoing plugging operations on location.		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404045540	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6860851
713400575	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6860842