

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 12/11/2024 Document Number: 404022147

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 46290 Contact Person: Dan Motisi Company Name: KP KAUFFMAN COMPANY INC Phone: (303) 825-4822 Address: 1700 LINCOLN ST STE 4550 Email: dmotisi@kpk.com City: DENVER State: CO Zip: 80203 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 322878 Location Type: Production Facilities Name: RUEBEL-61N65W Number: 2SWSE County: WELD Qtr Qtr: SWSE Section: 2 Township: 1N Range: 65W Meridian: 6 Latitude: 40.075920 Longitude: -104.627545

Description of Corrosion Protection

Carbon Steel pipelines are typically covered with a protective external coating, and are subject to rigorous fabrication, inspection, and quality control standards to reduce the occurrence of pipe and coating defects that can lead to external corrosion. While the likelihood of corrosion is minimal due to low operating pressures, KPK regularly inspects and pressure tests all lines to ensure corrosion is not occurring.

Description of Integrity Management Program

Production and upkeep of KPK's assets involves regular hands-on operation by KPK's field crews. These field crews not only maintain safe production, but also conduct routine inspections to confirm proper integrity of the production systems. While pipeline integrity issues are minimal due to pipeline materials and low operating pressure, KPK regularly inspects and pressure tests all lines to ensure pipeline integrity is maintained.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Construction of pipelines is generally not occurring. When necessary to remedy a pipeline issue, KPK typically assesses all conditions to determine the proper construction method. A combination of boring and open trench are utilized by KPK.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 478671 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 322878 Location Type: Well Site
Name: RUEBEL-61N65W Number: 2SWSE
County: WELD No Location ID
Qtr Qtr: SWSE Section: 2 Township: 1N Range: 65W Meridian: 6
Latitude: 40.075920 Longitude: -104.627545

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 03/26/1986
Maximum Anticipated Operating Pressure (PSI): 288 Testing PSI: 360
Test Date: 11/21/2019

OFF LOCATION FLOWLINE Abandonment Verification

Date: 08/10/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

The ground around the flowline was excavated in 50' segments to gain access to the flowline. During flowline abandonment, any liquids evacuated from the flowline were contained and disposed of per the requirements of rule 905. Any contaminated soil was properly disposed of and replaced with clean soil and graded to leave the area to look as undisturbed as possible.

OPERATOR COMMENTS AND SUBMITTAL

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 12/11/2024 Email: dmotisi@kpk.com

Print Name: Dan Motisi Title: Environmental Geologist

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:  Director of ECMC Date: 1/8/2025

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

404022147	Form44 Submitted
404022167	OFF-LOCATION FLOWLINE GIS SHP

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)