

Inspection Photos

API# 043-40014

Operator: **JAVERNICK OIL**

Inspection Date: 1/6/2025

County: **FREMONT**



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing northeast. The former oil and gas access road has not been reclaimed and revegetated.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API# 043-40014 | Date: 1/6/2025

Inspection Photos



Photo 2. Drone aerial photo facing northeast toward the former wellsite. There was an access road that went to the left down toward the Drapper 4 wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API# 043-40014 | Date: 1/6/2025

Inspection Photos



Photo 3. Drone aerial photo facing northeast toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API# 043-40014 | Date: 1/6/2025

Inspection Photos



Photo 4. Drone aerial photo facing north. There was an additional access road that goes to the Drapper 4 wellsite. This road has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API# 043-40014 | Date: 1/6/2025

Inspection Photos



Photo 5. Facing south along the access road shown in the previous photo. This road is not reclaimed or stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API# 043-40014 | Date: 1/6/2025