

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025



Photo # 1952 Entrance to location



Photo # 1976 Location

Date: 1/6/2025

Photo # 1953 Location

Photo # 1957 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025



Jan 6, 2025 at 12:32:31 PM
+39.565390,-108.232826 ±3.84m

Photo # 1975 Location



Jan 6, 2025 at 12:40:57 PM
+39.565092,-108.233259 ±2.94m

Photo # 1989 SW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025



Photo # 1990 SE corner of location



Photo # 1992 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025




Photo # 1993 NW corner of location



Photo # 1963 Wildlife hazard

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025




Photo # 1969 Wildlife hazard




Photo # 1974 Wildlife hazard



Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025



Photo # 1982 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 1983 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-65S97W/36SWSW (TR 14-36-597 PAD)

Location ID: 324303

Date: 1/6/2025



Photo # 1986 Open ended load line



Photo # 1987 Open ended load line

