

Final Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 306073

Well Name: AMATO #12-1

Inspection Document #: 718600148

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AMATO #12-1
Location ID: 306073



Photo 1. Photo taken at entrance to access road off SH53. Culvert remains in place at entrance to access road. Gravel remains inside and outside of fence..



Photo 2. Looking north down access road. Gravel remains inside fence near entrance of access road. Undesirable annual plant species such as Russian thistle, Kochia and noxious weeds Downy brome and Scotch thistle are dominant throughout the location.



Inspection Photos
Location Name: AMATO #12-1
Location ID: 306073



Photo 3. Looking east across the location. Well site has areas of bare soil. Desirable perennial vegetation has failed to establish. Undesirable annual plant species such as Russian thistle, Kochia and noxious weeds Downy brome and Scotch thistle are dominant throughout the location.



Photo 4. Looking north from the well site. See Photo 3 comments.



Inspection Photos
Location Name: AMATO #12-1
Location ID: 306073



Photo 5. Looking west from the well site towards access road. See Photo 3 comments.



Photo 6. Looking south from the well site. See Photo 3 comments.