

KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298



**Weeds. Lacking Stormwater BMPs.**




**Weeds. Lacking Stormwater BMPs.**

KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298



Gas calibration displayed




Calibration overdue



KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298



**Weeds. Lacking Stormwater BMPs.**



**Weeds. Lacking Stormwater BMPs.**



KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298



Faded chemical tank labels



Faded chemical tank labels





**KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298**



**When well sign is replaced additional information is required**



**Tank battery signs**



**KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298**



**Weeds**



**Weeds**



**KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298**



**Location from Southeast corner**



**Location from Northeast corner**



**KT Resources LLC  
Ant Hill Unit 16-22  
Location ID: 316298**



**Location from Northwest corner**



**Location from Southwest corner**