

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2024

Submitted Date:

01/03/2025

Document Number:

713400588**FIELD INSPECTION FORM**

Loc ID 334529	Inspector Name: Popejoy, Dusty	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1700 LINCOLN ST STE 3950</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>				<b>Findings:</b> <u>29</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, LARAMIE		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278342	WELL	PR	08/01/2022	GW	077-08902	MCDANIEL 2-15	PR
278343	WELL	PR	01/01/2011	GW	077-08903	MCDANIEL 2-16	PR
278344	WELL	PR	08/01/2017	GW	077-08904	MCDANIEL 2-10	PR
278346	WELL	PR	09/21/2015	GW	077-08906	MCDANIEL 2-9	PR
292512	WELL	PR	07/01/2018	GW	077-09415	MCDANIEL 2-9A	PR
292513	WELL	PR	03/17/2009	GW	077-09414	MCDANIEL 2-10C	PR
292514	WELL	PR	08/01/2019	GW	077-09413	MCDANIEL 2-10B	PR
292515	WELL	PR	09/01/2013	GW	077-09412	MCDANIEL 2-10A	PR
292516	WELL	PR	09/10/2014	GW	077-09411	MCDANIEL 2-9C	PR
292517	WELL	PR	05/06/2014	GW	077-09410	MCDANIEL 2-9B	PR
292518	WELL	PR	03/17/2009	GW	077-09409	MCDANIEL 2-15C	PR
292519	WELL	PR	05/01/2020	GW	077-09408	MCDANIEL 2-15B	PR
292521	WELL	PR	07/16/2009	GW	077-09406	MCDANIEL 2-16C	PR
292522	WELL	PR	03/17/2009	GW	077-09405	MCDANIEL 2-16B	PR
292523	WELL	PR	01/25/2016	GW	077-09404	MCDANIEL 2-16A	PR

**General Comment:**

CECMC Inspection Report Summary

On 12/31/2024 at approximately 14:30 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC McDaniel/2-9 Pad at Location ID #334529 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Signs/Marker - One wellhead is lacking required information, also another sign is illegible with a CA date of 02/4/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One wellhead is lacking required information, also another sign is illegible, refer to photos		
Corrective Action:	Comply with CECMC Signage rules	Date:	02/04/2025

Emergency Contact Number:

Comment: 1-800-891-6191/911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig Station - Pipe rail fencing		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Bradenhead	# 15				
Comment:	All Bradenhead valves are accessible with telemetry for monitoring				
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 16				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 15				
Comment:	All wells on plunger lift				
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 15				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 4				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	400 BBLS	STEEL AST		,	
Comment:	Tanks equipped with telemetry					
Corrective Action:					Date:	

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	278342	Type:	WELL	API Number: 077-08902 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278343	Type:	WELL	API Number: 077-08903 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278344	Type:	WELL	API Number: 077-08904 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278346	Type:	WELL	API Number: 077-08906 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	292512	Type:	WELL	API Number: 077-09415 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	292513	Type:	WELL	API Number: 077-09414 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	292514	Type:	WELL	API Number: 077-09413 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	292515	Type:	WELL	API Number: 077-09412 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292516	Type:	WELL
API Number:	077-09411	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292517	Type:	WELL
API Number:	077-09410	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292518	Type:	WELL
API Number:	077-09409	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292519	Type:	WELL
API Number:	077-09408	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292521	Type:	WELL
API Number:	077-09406	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292522	Type:	WELL
API Number:	077-09405	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	292523	Type:	WELL
API Number:	077-09404	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing well on plunger lift		

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						
		Ditches				
		Compaction				

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker for corrective action.</a>	popejoyd	01/03/2025
<a href="#">Limited storm water inspection due to snow cover</a>		

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404047842	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863138">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863138</a>
713400589	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863137">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6863137</a>