

# Final Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 305399

Well Name: AMATO #22-1

Inspection Document #: 718600144

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: AMATO #22-1  
Location ID: 305399



**Photo 1.** Photo taken looking east at entrance of location. Cattle guard remains in place off of sh52. Gravel has not been removed from site.



**Photo 2.** Looking north across well site. Desirable vegetation has failed to establish and well site has bare earth patches. Undesirable plant species such as Russian thistle, Kochia, and noxious weeds such as Downy Brome and Scotch thistle are dominant.



Inspection Photos  
Location Name: AMATO #22-1  
Location ID: 305399



**Photo 3.** Picture taken looking west from well site. See Photo 2 comments.



**Photo 4.** Photo looking south across wellsite towards former access road. Undesirable and noxious weeds are dominant on access road.





Inspection Photos  
Location Name: AMATO #22-1  
Location ID: 305399



**Photo 5.** Example of groundcover taken at well site. Vegetative cover consists of undesirable or noxious plant species. Cobble and gravel is present.



**Photo 6.** Looking west from the south side of well site. Class 2 noxious weed Scotch thistle is present on location.

