

# Final Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 305073

Well Name: AMATO #11-1

Inspection Document #: 718600150

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: AMATO #11-1  
Location ID: 305073



**Photo 1.** Looking south from nearby tank battery (Loc ID #409555) along former access road. Some desirable perennial plant species have established. Noxious weeds (Scotch thistle and Downy brome) are present. Undesirable plant species Russian thistle and Kochia are present throughout the location.



**Photo 2.** Looking east down former access road toward well site. See photo 1 comments.



Inspection Photos  
Location Name: AMATO #11-1  
Location ID: 305073



**Photo 3.** Looking north from wellsite. Nearby pasture has been mowed, well site does not appear to have been mowed. See Photo 1 comments.



**Photo 4.** Photo looking south from wellsite. See Photo 1 comments.





Inspection Photos  
Location Name: AMATO #11-1  
Location ID: 305073



**Photo 5.** Looking east from wellsite. See Photo 1 comments.



**Photo 6.** Looking west from the southeast side of well site. List B noxious weed Scotch thistle is present throughout location. Some bare areas are present.

