

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2025

Submitted Date:

01/10/2025

Document Number:

715201433

FIELD INSPECTION FORM

Loc ID 321768 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207953	WELL	PR	12/01/1989	GW	017-06888	ARAPAHOE UNIT 160 (13-16)	WK

General Comment:

[SE Compliance Specialist Brian Welsh](#) conducted a routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank needs labeling if it to be used		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Battery is 3/4 fenced with wire on east side and metal panels on west side		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	Horizontal Heater Treater	# 1	
Comment:	Treater on south side of meter run		
Corrective Action:		Date:	
Type:	Vertical Heater Treater	# 1	
Comment:	Vertical treater has fire tube removed and used as a vertical separator		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier, chemical drum w/containment, gas powered circ pump at battery		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter shed on north side of Horizontal treater		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Lufkin 228 Mark II		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.833600,-102.127470
Comment:	Black tank on south side of oil tanks				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		38.833600,-102.127470
Comment:	Central tank battery for Arapahoe Unit (159, 160, 161, 162) 2-Tan tanks and 2-Blue tanks				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:		
Corrective Action:		Date:

Wells Served By Facilities Above

AirsID

API Number
017-06783
017-06888
017-06821
017-06820

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 207953 Type: WELL API Number: 017-06888 Status: PR Insp. Status: WK

Producing Well

Comment: [Central tank battery for Arapahoe Unit \(159, 160, 161, 162\) 600' W @ 38.833600/-102.127470](#)

Corrective Action:

Date:

Workover

Comment: [ECWS on location for well repairs](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715201486	workover rig on location	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6871422
715201487	tank battery	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6871424