

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2025

Submitted Date:

01/10/2025

Document Number:

715800525

FIELD INSPECTION FORM

Loc ID 317862 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
Norton, Mathew		mnorton@kpk.com	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240083	WELL	PR	08/01/2019	OW	123-07871	CARL R DEEPE C 1	PR

General Comment:

[This is a wellsite audit/inspection.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fab. angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment: fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment		# 1				
Comment:	electric panel meter box and transformers					
Corrective Action:					Date:	
Type: Prime Mover		# 1				
Comment:	electric motor					
Corrective Action:					Date:	
Type: Bradenhead		# 1				
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240083 Type: WELL API Number: 123-07871 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/13/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Routine Audit/Inspection Any corrective actions from previous Inspections that have not been addressed are still applicable Weather: Cloudy Temperature: 42* Location: Dry with some snow & mud .	revasr	01/10/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800526	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6871808