

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2025

Submitted Date:

01/06/2025

Document Number:

715800494

FIELD INSPECTION FORMLoc ID 318207 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240872	WELL	PR	04/27/1976	OW	123-08660	DITLEV-SIMONSEN C 1	SI

General Comment:[This is a follow up wellsite audit/inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	Excavation stock pile/debris sits to the east of the wellsite set on plastic liner that is starting to disintegrate & needs to be removed.	
Corrective Action:	Install/repair required BMPs per Rule 1002.f.(2)C	Date: 05/31/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Chainlink topped with barb wire	
Corrective Action:		Date:
Type	OTHER	
Comment:	The open pipeline excavation has Temp. orange construction fence.	
Corrective Action:		Date:
Type	PUMP JACK	
Comment:	Shares fence with the WH, Angle iron.	
Corrective Action:		Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box & transformers		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	240872	Type:	WELL	API Number:	123-08660	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: SI valves are closed & electric panel is shut off.									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 09/03/2024									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type:									
End Surf Csg Pressure: 0									
Comment: Plumbed to surface									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary.</p> <p>On Monday 1-6-2025 at approximately 1450 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Follow up to FIR doc # 716400148</p> <p>Operator: KP Kauffman</p> <p>Location ID # 318207</p> <p>Well Name: Ditlev-Simonsen C1</p> <p>API # 05-123-08660</p> <p>County: Weld</p> <p>Weather: Cloudy & cold</p> <p>Location: Dry</p> <p>Temperature: 36*</p> <p>While there, I observed a wellsite, SI at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues have been addressed:</p> <p>605.g Signs Gen. Cond: has been addressed.</p> <p>913.B.i fence or cover open excavations: has been addressed.</p> <p>During this inspection, I observed the following possible compliance issues have not been addressed:</p> <p>1002.f.(2)C: CA date 5-31-2024.</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> <p>Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	01/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404049428	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865651
715800495	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865642