


KT Resources LLC
 WRD Wyatt-62N97W 25SESE
 Location ID: 336393

Jan 13, 2025 at 2:56:25 PM



25-44. Gas calibration overdue.

Jan 13, 2025 at 2:57:41 PM



Sign along flow line. No production equipment.

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



25-44W. No calibration card.



When replaced additional information is required

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Debris



Previous spill and stained soils

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Soil staining

Soil staining

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Damaged tank label



Oily waste. Damaged tank label.

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Debris



Illegible label

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Unused equipment



Illegible label

**KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393**



When replaced additional information is required



Erosion and sediment migration

KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393



Vehicle tracking



Erosion and vehicle tracking

**KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393**



Location from Southwest corner and entrance



Location from Northwest corner and entrance

**KT Resources LLC
WRD Wyatt-62N97W 25SESE
Location ID: 336393**



Location from Northeast corner



Location from Southeast corner