

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2025

Submitted Date:

01/15/2025

Document Number:

698603030

**FIELD INSPECTION FORM**

Loc ID 303899 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253767	WELL	PR	03/21/1995	GW	125-07645	JOE BROPHY 8-14	PR

**General Comment:**

[Follow-Up Inspection. Inspector is completing Follow-up inspection as required by FIRR. Follow-up inspection will ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 11/01/24 FIR document number 698602624.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at wellhead location.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Emergency contact information posted on Lease sign.		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	

Type: Dehydrator	# 1		
Comment:	Dehydrator located at well location on wellhead sales line to gas meter run inlet.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve closed. Casing valve open.  Well is venting at the cap. Notified Field Foreman by text at 11:02 AM 11-1-2024.  Corrective action has not been performed or are insufficient to prevent recurrence. Assigned corrective action date remains the same to document period of non-compliance.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: <u>11/02/2024</u>

**Venting:**

Yes/No	YES		
Comment:	Wellhead is venting at the cap.  Corrective action has not been performed or are insufficient to prevent recurrence. Assigned corrective action date remains the same to document period of non-compliance.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: <u>11/02/2024</u>

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253767 Type: WELL API Number: 125-07645 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Casing production. Tubing valve closed. Casing valve open.

Electronic Well File reflects last Production/Status reported 11/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Inspector completed Follow-up inspection 01/14/2025 as required by FIRR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 11/01/24 FIR document number 698602624. Corrective actions have not been performed or are insufficient to prevent recurrence. Assigned corrective action dates remains the same to document period of non-compliance.	stjohnw	01/15/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603033	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876369">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876369</a>
698603034	11/01/24 FIR document number 698602624.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876370">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876370</a>
698603035	1/14/25 FIR document number 698603030.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876371">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6876371</a>