

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2025

Submitted Date:

01/15/2025

Document Number:

711901751

FIELD INSPECTION FORM

Loc ID 312141 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10017
Name of Operator: CHACO ENERGY COMPANY
Address: P O BOX 1587
City: DENVER State: CO Zip: 80201

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Nelson, Matt	303-981-3840	matt@chacoenergy.com	Inspections/Ops. Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218838	WELL	PR	03/01/2020	OW	075-05599	WRITEBOL 3	PR

General Comment:

[WO - RIG ON LOCATION - INSPECT AND REPAIR](#)

Inspected Facilities

Facility ID: 218838 Type: WELL API Number: 075-05599 Status: PR Insp. Status: PR

Producing Well

Comment: WO - INSPECT AND REPAIR

Corrective Action:

Date:

Workover

Comment: INSPECT AND REPAIR - CORRECTED VALVE PROBLEM - (1) DAY ON WO COMPLETED

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>WO - REPAIR COMPLETED</u>	schureky	01/15/2025