

Inspection Photos
Location Name: UPRC 33-11J5
Location ID: 329677



Energy & Carbon Management Commission
40.17959, -104.67033, 1466.5m, 28°
Jan 15, 2025 12:15:56



Energy & Carbon Management Commission
40.17956, -104.67035, 1466.2m, 24°
Jan 15, 2025 12:16:06

Photo 1: Wellhead Sign, operator name no longer legible

Photo 2: Dead, overgrown vegetation

Inspection Photos
Location Name: UPRC 33-11J5
Location ID: 329677



Photo 3: Dead, overgrown vegetation

Photo 4: Dead, overgrown vegetation

Inspection Photos
Location Name: UPRC 33-11J5
Location ID: 329677



Photo 5: Tank Battery Sign

Photo 6: Dead, overgrown vegetation/debris

Inspection Photos
Location Name: UPRC 33-11J5
Location ID: 329677



Photo 7: Dead, overgrown vegetation/debris



Photo 8: Dead, overgrown vegetation/debris. Not maintained earth berm

Inspection Photos
Location Name: UPRC 33-11J5
Location ID: 329677



Energy & Carbon Management Commission
40.18172, -104.67775, 1475.0m, 125°
Jan 15, 2025 12:22:37

Photo 9: Dead, overgrown vegetation/debris