

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2024

Submitted Date:

01/09/2025

Document Number:

717000241**FIELD INSPECTION FORM**Loc ID 320071 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		alexander.ahmadian@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Supervisor, ECME		jason.gomez@state.co.us	
,		conor.pesicka@state.co.us	
, COGCC		mike.leonard@state.co.us	
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202495	WELL	SI	12/01/2019	GW	001-07900	CHAMPLIN 485 AMOCO 1	SI

General Comment:[Follow-up inspection DOC# 717000102 / No equipment has been replaced](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment: No BMP's in place to control Storm water sediment from pit berm from leaving location.

Corrective Action: Rule 1002 f(2)c. BMPs-.Corrective action date 2/7/2025, see photos 7-17

Date: 02/07/2025

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment: Corrective Action: Date:

Type: Ancillary equipment

3

Comment: Corrective Action: Date:

Type: Bird Protectors

2

Comment: Corrective Action: Date:

Type: Vertical Heated Separator

2

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

100 BBLS

FIBERGLASS AST

,

Comment: Corrective Action: Date: **Paint**

Condition

Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		39.928302,-104.150805
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number	API Number	AirsID
001-07900		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202495 Type: WELL API Number: 001-07900 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/08/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to the surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary</p> <p>On Tuesday December 31st 2024 at approximately 11:37am. I, Inspector Chane Finkenbinder, conducted an on-site Follow-up inspection doc# 717000102</p> <p>Operator: RENEGADE OIL & GAS</p> <p>Location name: CHAMPLIN 485 AMOCO #1</p> <p>API # 05-001-07900</p> <p>Location ID #: 320071</p> <p>County: Adams</p> <p>While there, I observed a Shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>All corrective actions from Doc#717000102 have addressed except that there appears to not be a any BMPs in place.</p> <p>Rule 1002 f(2)c. BMP's in place to control storm water sediment form pit berm from leaving location.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	01/09/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404053688	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6870233
717000245	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6870217