

Inspection Photos

API: 061-06021

Operator: CIMARRON OIL & GAS CO INC

Inspection Date: 1/14/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast at the former wellsite. There appears to have been a historic impact where vegetation is not establishing. There are abandoned pipe risers shown at red arrows.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06021 | Date: 1/14/2025

Inspection Photos




Photo 2. There are abandoned pipe risers shown at red arrows.



Inspection Photos



Photo 3. Facing northeast at the location. There are abandoned pipe risers shown at red arrows.



Inspection Photos



Photo 4. Facing northeast. There is a fiberglass pipe on the surface approximately 150' in length.



Inspection Photos



Photo 5. Facing back to the west. There appears to have been a historic spill impact where vegetation is not establishing and erosion has occurred.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06021 | Date: 1/14/2025

Inspection Photos



Photo 6. Facing west at the east side of the location. There is multiple abandoned pipe risers and a cement pad.



Inspection Photos



Photo 7. Facing southeast at the location. There appears to have been an historic spill impact in this area with no vegetation establishment. There is a dilapidated shed that remains.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06021 | Date: 1/14/2025

Inspection Photos



Photo 8. Just north of the wellsite (~500') is another impacted area with no vegetation establishment and erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06021 | Date: 1/14/2025