

Final Reclamation and Stormwater Inspection

January 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 459332

Well Name: AMATO-61N66W TANK/1SEW

Inspection Document #: 718600146

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: AMATO-61N66W
TANK/1SENW
Location ID: 459332



Photo 1. Photo taken looking east at entrance of location. Cattle guard remains in place off of SH52. Gravel has not been removed from site.



Photo 2. Looking west across tank battery. Desirable vegetation has failed to establish. Undesirable plant species such as Russian thistle, Kochia, and noxious weeds such as Downy Brome and Scotch thistle are dominant.

Inspection Photos
Location Name: AMATO-61N66W
TANK/1SEW
Location ID: 459332



Photo 3. Picture taken looking east across tank battery location. See Photo 2 comments.



Photo 4. Looking at north side of tank battery. Gravel remains on location.