

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2025

Submitted Date:

01/17/2025

Document Number:

708905494

FIELD INSPECTION FORM

Loc ID: 334848
Inspector Name: Smelser, Wayne
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED
Findings:
 34 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|------------------------------------|---------|
| , TEP | | COGCCInspectionReports@terraep.com | |
| Toews, Wesley | | wtoews@blm.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 210913 | WELL | PR | 09/07/1998 | CBM | 045-06671 | FEDERAL 0-4-7-94-W | PR |
| 297147 | WELL | PR | 06/30/2010 | GW | 045-16322 | FEDERAL RWF 334-4 | PR |
| 297148 | WELL | PR | 06/30/2010 | GW | 045-16323 | FEDERAL RWF 34-4 | PR |
| 297149 | WELL | PR | 06/30/2010 | GW | 045-16324 | FEDERAL RWF 543-4 | PR |
| 297150 | WELL | PR | 06/30/2010 | GW | 045-16325 | FEDERAL RWF 333-4 | PR |
| 297151 | WELL | PR | 07/31/2010 | GW | 045-16326 | FEDERAL RWF 33-4 | PR |
| 297152 | WELL | PR | 06/30/2010 | GW | 045-16327 | FEDERAL RWF 43-4 | PR |
| 297153 | WELL | PR | 06/30/2010 | GW | 045-16328 | FEDERAL RWF 544-4 | PR |
| 297154 | WELL | PR | 06/30/2010 | GW | 045-16329 | FEDERAL RWF 444-4 | PR |
| 297155 | WELL | PR | 06/30/2010 | GW | 045-16330 | FEDERAL RWF 344-4 | PR |
| 297156 | WELL | PR | 05/16/2011 | GW | 045-16331 | FEDERAL RWF 44-4 | PR |
| 297157 | WELL | PR | 06/30/2010 | GW | 045-16332 | FEDERAL RWF 533-4 | PR |
| 297158 | WELL | PR | 06/30/2010 | GW | 045-16333 | FEDERAL RWF 433-4 | PR |
| 297159 | WELL | PR | 06/30/2010 | GW | 045-16334 | FEDERAL RWF 443-4 | PR |
| 297160 | WELL | PR | 06/30/2010 | GW | 045-16335 | FEDERAL RWF 343-4 | PR |

General Comment:

CECMC Inspection Report Summary

On 01/13/2025 at approximately 14:14 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL 0-4-7-94-W Pad.

Location # 334848 in Garfield County Colorado.

Please refer to inspection 708904140 conducted on 06/27/2024 & inspection 708905404 conducted on 01/01/2025, previous corrective action has been completed.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 255 yards from Spruce Creek.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

| | | | |
|--------------------|-------------|--|-------|
| Lease Road: | | | |
| | Type Access | | |
| comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|--|--|-------|
| Signs/Marker: | | | |
| | Type WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| | Type TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| | Type OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks. | | |
| Corrective Action: | | | Date: |
| | Type BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| | Type CONTAINERS | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|---------------------------|--|-------------|
| Emergency Contact Number: | | | |
| | Comment: 911/970-285-9377 | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|--|--|-------|
| Fencing/: | | | |
| | Type OTHER | | |
| Comment: | Chemical tanks, liquid nitrogen tank & catalytic heater - hog panels | | |
| Corrective Action: | | | Date: |
| | Type WELLHEAD | | |
| Comment: | Hog panels | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|------------|-------|--|
| Type | SEPARATOR | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 15 | | |
| Comment: | Taylor plugs located on all bradenhead, bradenhead valves are accessible | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 15 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Liquid nitrogen tank Unable to locate FORM 4 SUNDRY for equipment/not in compliance with CECMC rules | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 9 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 15 | | |
| Comment: | All wells on plunger lift | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Catalytic heater | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 15 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------------------|----------|------------------|---------|--------|
| CONDENSATE | 1 | 200 BBLs | HEATED STEEL AST | | |
| Comment: | Tank equipped with telemetry | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|------------------------------|---------------------|---------------------|-------------|--------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | | | |
| Comment: | Centralized containment | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , |
| Comment: | Tank equipped with telemetry | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | 80 bbl | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficent | | | |
| Comment: | Centralized containment | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | | |
|--|---------------------------------|-------|------|-------------|-----------|---------|-------|---------------|----|--|
| Facility ID: | 210913 | Type: | WELL | API Number: | 045-06671 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297147 | Type: | WELL | API Number: | 045-16322 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297148 | Type: | WELL | API Number: | 045-16323 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297149 | Type: | WELL | API Number: | 045-16324 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297150 | Type: | WELL | API Number: | 045-16325 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297151 | Type: | WELL | API Number: | 045-16326 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297152 | Type: | WELL | API Number: | 045-16327 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |
| Facility ID: | 297153 | Type: | WELL | API Number: | 045-16328 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Producing, well on plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12 | | | | | | | | | | |

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297154 | Type: | WELL | API Number: | 045-16329 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297155 | Type: | WELL | API Number: | 045-16330 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297156 | Type: | WELL | API Number: | 045-16331 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297157 | Type: | WELL | API Number: | 045-16332 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297158 | Type: | WELL | API Number: | 045-16333 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297159 | Type: | WELL | API Number: | 045-16334 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297160 | Type: | WELL | API Number: | 045-16335 | Status: | PR | Insp. Status: | PR |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

| Producing Well | | | |
|-----------------------|---------------------------------|--|-------|
| Comment: | Producing, well on plunger lift | | Date: |
| Corrective Action: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------|
| | | Compaction | | | | |
| | | Culverts | | | | |
| Compaction | | | | | | |
| | | | | Material Handling And Spill Prevention | | Chemical tank containments |
| Berms | | | | | | |
| | | Ditches | | | | |

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Please refer to Equipment for comments | smelserw | 01/17/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 708905495 | Inspection 708905494 photo log | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880574 |