

Inspection Photos
Owen 12-1 Flowline
Spill ID 485393/Remediation 37867



ECMC Environmental Inspection
40.2354, -104.95729, 1481.9m, 253°
12/11/2024 09:58:38 AM



ECMC Environmental Inspection
40.23518, -104.95737, 1480.9m, 347°
12/11/2024 09:59:26 AM

Photo 1 –

Photo 2 -

Inspection Photos
Owen 12-1 Flowline
Spill ID 485393/Remediation 37867



Photo 3 –



Photo 4 -

Inspection Photos
Owen 12-1 Flowline
Spill ID 485393/Remediation 37867



Photo 5 –



Photo 6 -

Inspection Photos
Owen 12-1 Flowline
Spill ID 485393/Remediation 37867



Photo 7 –



Photo 8 -

Inspection Photos
Owen 12-1 Flowline
Spill ID 485393/Remediation 37867



Photo 9 –



Photo 10 -

